



Aug. 1899
WOBURN
MASS.


Situated 3 Miles N. of
Woburn Common



24




PANTASOTE LEATHER CO.



No Exposure.

24


24



24

Vacant.

CHEMICAL ACIDS.



Run West and On. 3' out. Workmen has 3 Boor
Gases, Test and Run. Steam. Lights. Etc.
The first well between. Condensers. Etc.
200 feet. For Muriatic. Sulfuric Acid. Etc.
2. Then as before. Sulfuric Acid. Etc.
Condensers. Etc. See map and see
Note. Sulfuric Acid. Etc. Etc. Etc. Etc.
RECTIONS.

RISK

MAD FILED
31 JUL 1955

Scale of Feet.
0 50 100 150